Oil Field Environmental Incident Summary

Responsible Party: WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: P DAM STATE 155-99-4-16-21-14H

Field Name: EPPING Well File #: 28542

Date Incident:11/11/2016Time Incident:10:30Facility ID Number:County:WILLIAMSTwp: 155Rng: 99Sec: 16Qtr:

Location Description:

Submitted By: Corissa Zimmer Received By:

Contact Person: Corissa Zimmer

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:0.4 MileDistance Nearest Water Well:0.4 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 1 Gallons

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 11/28/2016 Clean Up Concluded: 11/21/2016

Risk Evaluation:
None noted

Areal Extent:

Approximately 270 feet from the well to the north west, off location, with a width up to 100 feet.

Potential Environmental Impacts:

None noted

Action Taken or Planned:

Equipment on location was cleaned off, and impacted grass will be mowed and disposed of. Whiting is currently looking into more information about the time frame and what could have loosened the packing.

Wastes Disposal Location: An approved location, possibly Secure.

Agencies Involved: Michael Haupt with the North Dakota Department of Trust Lands

Updates

Date: 11/14/2016 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Follow-up is required.

Date: 11/16/2016 Status: Inspection Author: Kannenberg, Derek

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the well site, and a light film of oil was observed on vegetation. Spoke with Corissa about the site, and she informed me that they would mow the site and dispose of the vegetation. Follow-up required to confirm mowed vegetation and proper disposal.

Date: 11/22/2016 Status: Inspection Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 3:38 p.m. Weather was foggy with wind out of the NE at 15 mph. Temperature was 32 degrees F. The area of impact is located NW of the pad in a grassland/ pasture area. The vegetation has not been mowed or removed yet. Pictures were collected. Additional follow-up needed to ensure the impacted vegetation is removed.